



FOR CENTRAL  
OFFICE  
USE ONLY

ESTABLISHMENT NUMBER

Establishment Name: Eagle Inn  
 Physical Address: 2811 E Marshall City: Charleston Zip: 63834  
 Mailing Address: \_\_\_\_\_ City: \_\_\_\_\_ Zip: \_\_\_\_\_  
 County: 133 This inspection is a(n)  Initial  Annual  Follow-up Telephone: 683-3900  
 No. of Stories: 1 No. of Rooms: 19 Is the current lodging license displayed?  Yes  No  N/A - new

**Rooms Inspected:** 119, 123, 126, 129, 130, 114, 115, 116, 121  
**Water Supply**  Private  Public  
 Water sample taken  Yes  No  
**Wastewater**  Private  Public  
 Regulated by:  DHSS  DNR  
**Swimming Pools/Spas (check all that apply)**  
 Indoor pool  Outdoor pool  Spa  Pool larger than 2000 square feet

**Please check if the following local ordinances apply**  
 Fire Safety  Electrical Wiring  
 Plumbing  
 Swimming Pools/Spas  
 Fuel Burning Appliances

**New Lodging Establishments**  N/A

Smoke detectors hardwired  Yes  No  N/A  
 Fire alarm system installed  Yes  No  N/A  
 Sprinkler system installed  Yes  No  N/A  
 Swimming Pool Certified  Yes  No  N/A  
 Building Certified to National Standards or Occupancy Permit  Yes  No  
 Historical Building  Yes  No  N/A

Based on an inspection this day, the items marked "Out" below identify noncompliance in operations or facilities which must be corrected prior to issuance or renewal of your lodging license. Failure to comply with any time limits for corrections specified in this notice may result in revocation of your lodging license and/or prosecution. Owners may request a hearing before the Department Director upon filing a written request within ten days after receipt of this notice. (RSMo 315.005-065, 19 CSR 20-3.050)

		In=In Compliance				Out=Not In Compliance, explain on additional page(s)				NO=Not Observed				N/A=Not Applicable			
		In	Out	NO	N/A	Section A & B: Water Supply & Wastewater				Section E: Fire Safety							
1. Approved source, construction and operation		X				1. Textiles, hangings and mirrors				X							
2. Complies with water quality standards		X				2. Fire extinguisher type, inspected, and location				X							
3. Chlorinator maintained and operated properly					X	3. Vertical openings fire-rated, self-closing							X				
4. Wastewater operation and maintenance		X				4. Doors, self-closing and fire-rated							X				
<b>Section C: Sanitation/Housekeeping</b>						5. Smoke detectors hardwired, installed, good repair					X						
1. Walls, floors and ceilings in good repair			X			6. Evacuation route and plan, installed, available							X				
2. Housekeeping practices and furnishings			X			7. Stairs and ramps, maintained, storage							X				
3. Towels and bed linens clean			X			8. Means of egress, number, maintained				X							
4. Mattresses and box springs clean		X				9. Handrails and balconies maintained and appropriate							X				
5. Pest control procedures			X			<b>Section F: Swimming Pools/Spas</b>											
6. Ice machines, scoops, liners clean & protected			X			1. Fence, gate adequate, proper closure mechanism							X				
7. Garbage storage and disposal		X				2. Boundary line, pool depth properly marked											
8. Premises maintained, plant growth controlled		X				3. Deck is clean and in good repair											
<b>Food Inspection conducted according to 19CSR20-1.025</b>						4. Lifesaving equipment adequate, good repair											
9. Food, equipment and single service/use		X				5. Pool clarity, pH, disinfectant, & temp. maintained											
10. Food protected from contamination		X				6. Steps, ladders, and handrails installed, good repair											
11. Facilities to wash, rinse and sanitize					X	7. Adequate ventilation											
12. Handwashing facilities/hygienic practices					X	8. Electrical outlets, proper protection & distance											
<b>Section D: Life Safety</b>						9. Records maintained and signs posted											
1. Combustible/toxic items usage and storage		X				10. First aid kit available											
2. Building maintained to assure safe conditions		X				11. Lighting adequate and in good repair											
3. CO detectors hardwired, installed, good repair		X				<b>Section G: Plumbing/Mechanical</b>											
4. GFCI, outlets & switches installed, good repair			X			1. Equipment adequate, good repair											
5. Exit signs installed, good repair					X	2. Ventilation adequate, plumbing, restrooms					X						
6. Emergency lighting installed, good repair					X	3. T & P relief valves adequate, good repair					X						
7. Electric panel protected, labeled, good repair			X			4. Relief valve discharge pipes installed, adequate				X							
<b>Required Annual Third Party Inspections</b>						5. Backflow, air gaps, no cross connections				X							
1. Fire Alarm System						<b>Section H: Heating &amp; Cooling</b>											
2. Sprinkler System						1. Unvented fuel-burning appliance/space heater							X				
3. Local Fire and Building Codes/Ordinances						2. Fire resistant room or sprinkler head				X							
4. Current Boiler/Pressure Vessels MDPS Certification						3. Location of heating/cooling units				X							
5. Backflow Device(s) Test						4. Ventilation of appliances and utility rooms				X							
6. Liquid Propane Leak Test						5. Operation and condition adequate				X							

INSPECTED BY (PRINT NAME and SIGN): Derek Hanaas Darzharmarin EPHS NUMBER: 1126 AGENCY: MO DHSS TELEPHONE: 573-730-1310  
 LICENSING YEAR: 20 19 / 20 20 APPROVED  YES  NO DATE INSPECTED: 8-29-19 FOLLOW UP DATE: 9-17-2019  
 RECEIVED BY (PRINT NAME AND TITLE and SIGN): Jitendra Patel PAGE 1 OF 3



Establishment Name	Physical Address	City
Eagle Inn	2811 E Marshall	Charleston
Section Reference	Observations, comments, and corrective measures	
	<u>Room 130</u>	
D-4	GFCI Open ground	
C-1	Crack in bathroom ceiling	
C-1	Water damage around A/C unit	
C-2	Microwave soiled	
C-2	Splatter on wall by AC unit	
E-5	Smoke detector not plugged in	
C-5	Cob webs in ceiling corner over nightstand	
C-1	Ceiling damaged over door and windows	
C-1	Baseboards detached	
C-2	Musty smell in room	
	<u>Room 129</u>	
C-1	Bathroom ceiling water damaged	
C-1	Wall damaged by tub	
C-2	Refrigerator soiled with food debris	
C-5	Dead bugs behind bed	
C-5	Light visible under door	
G-2	Exhaust fan not working	
C-1	Crack in ceiling by door	
	<u>Room 126</u>	
C-2	Musty smell in room	
C-1	Wall damaged by AC unit	
C-3	Stain on box spring covers	
C-2	Chair cushion stained	
	<u>Room 123</u>	
C-2	White residue along baseboards	
C-5	Light visible around door	
C-6	Ice bucket lid missing	
	<u>Room 119</u>	
C-2	Musty smell in room	
C-5	Light visible under door	
G-2	Exhaust fan not working	
C-5	Dead bugs along base boards	
C-2	White residue under left bed	
C-5	Cobwebs behind TV stand	
C-2	Trash behind TV stand	
C-1	Mold on ceiling patch in bathroom	

INSPECTED BY

RECEIVED BY

DATE

*Denise Jodie Marcar*

*[Signature]*

8-29-19



Section Reference	Observations, comments, and corrective measures
Establishment Name: <u>Eagle Inn</u> Physical Address: <u>2811 E Marshall</u> City: <u>Charleston</u>	
	<u>Room 116</u>
D-4	GFI not working
G-2	Exhaust fan in bathroom not working
G-6	Ice bucket lid missing
G-2	White stain on carpet by nightstand next to the window
	<u>Room 115</u>
G-2	Musty smell in room
G-2	Exhaust fan in bathroom not working and detached from wall
G-2	Freezer soiled with food debris
G-5	Daylight visible under exterior door
E-5	Smoke detector not working, wiring not connected
G-1	Wall damaged behind bed by door
	<u>Room 114</u>
G-1	Wall damaged near ceiling over shower
E-5	Smoke detector not working, wiring not connected
G-2	Lamp shade on desk stained
	<u>Room 121</u>
G-1	Faucet leaking
G-5	Daylight visible under exterior door
G-1	Ceiling damaged over bed by exterior door
	<u>Ice machine room</u>
G-2	Floor soiled with mold and debris
G-5	Cobwebs over ice machine
	<u>Laundry room/storage</u>
D-7	Black barrels and box of toilet paper blocking access to electrical panels
G-3	Water heater T&P valve tag missing

INSPECTED BY <u>Derzhon Jodie Maroun</u>	RECEIVED BY <u>[Signature]</u>	DATE <u>8-29-19</u>
---	-----------------------------------	------------------------